

Opening forces or failure of commercially available equine headcollars and other safety devices

Marlin, David J; Pickles, Kirstie; Ferro de Godoy, Roberta; Williams, Jane M

Published in:

Proceedings of the Institution of Mechanical Engineers, Part P: Journal of Sports Engineering and Technology

Publication date:

2021

The re-use license for this item is:

CC BY-NC-ND

This document version is the:

Peer reviewed version

The final published version is available direct from the publisher website at:

[10.1177/17543371211039610](https://doi.org/10.1177/17543371211039610)

Citation for published version (APA):

Marlin, D. J., Pickles, K., Ferro de Godoy, R., & Williams, J. M. (2021). Opening forces or failure of commercially available equine headcollars and other safety devices. *Proceedings of the Institution of Mechanical Engineers, Part P: Journal of Sports Engineering and Technology*, 175433712110396. <https://doi.org/10.1177/17543371211039610>

1 **Opening Forces or Failure of Commercially Available Equine Headcollars and Other Safety Devices**

2
3 D.J. Marlin¹, K. Pickles², R. Ferro de Godoy³ and J.M. Williams⁴

4
5 ¹D.J. Marlin, AnimalWeb Ltd, Cambridge, UK, CB4 0WZ
6 dm@davidmarlin.co.uk

7
8 ²K.J. Pickles, Chine House Veterinary Hospital, Cossington Rd, Sileby, Leicestershire, UK, LE12 7RS,
9 United Kingdom.

10
11 ³R. Ferro de Godoy, Writtle University College, Lordship Road, Writtle, Chelmsford, Essex, UK, CM1
12 3RR

13
14 ⁴J.M. Williams, Hartpury University, Hartpury, Gloucestershire, UK
15 Hartpury University, Department of Equine Science, GL19 3BE, Hartpury, United Kingdom.

16
17

18 **ABSTRACT**

19 A recent survey by our group indicated that headcollar (halter, USA) related incidents in which
20 horses were injured may be common. Furthermore, 134 incidents involving horse fractures and 167
21 fatalities were reported. Headcollar design and materials vary markedly from traditional leather to
22 'safety' headcollars and safety devices. Despite their almost universal use, there appears to be little
23 study of how these items function or specifications for performance. The aim of the present study
24 was to select a range of commercially available headcollars of standard design and a number of
25 safety devices, including baler twine. The latter is widely used by equestrians to attach a horse by a
26 headcollar to a lead rope and in turn to a fixture and perceived to increase safety. Devices were
27 subjected to increasing load in the poll to lead-rope attachment axis, i.e. to simulate a horse pulling
28 backwards, using a custom-made steel rig incorporating an electric 1000kg winch. The force was
29 increased incrementally until either the headcollar or device opened or failed. The lowest mean
30 opening force was for a safety headcollar ($357\pm 50\text{N}$; $n=6$; $\text{mean}\pm\text{SD}$); equivalent to a load of
31 approximately 36kg. The highest breaking force was $5798\pm 265\text{N}$ for one of the eight different
32 webbing headcollars tested ($n=6$). Breaking for safety devices ranged from $354\pm 121\text{N}$ ($n=6$) for 'fine'
33 baler twine to $1348\pm 307\text{N}$ ($n=6$) for a 'heavy duty' baler twine. Variability in opening force was
34 lowest in two of the webbing headcollars ($\text{CV} < 5\%$) despite these having very high breaking points
35 ($> 3500\text{N}$). The greatest variability was found for fine baler twine ($\text{CV} = 34\%$) and one of the
36 commercial safety devices ($\text{CV} = 38\%$). The range of opening forces and the variability in opening
37 forces for standard headcollars, safety headcollars and safety devices is a cause for concern and may
38 give horse owners/handlers a false sense of security of safety, and actually predispose horses and
39 handlers to an increased risk of injury.

40

41 **KEYWORDS:** horse; restraint; safety; force; tack; injury

42 INTRODUCTION

43 Headcollars or halters are pieces of tack that are fitted to a horse's head to allow control of the
44 horse. Headcollars are primarily used for husbandry procedures such as tying horses up, keeping
45 them in one place by a handler, for example for foot care or veterinary examination, or leading
46 horses from the ground. A recent survey of almost 5615 equestrians reported that 88% used a
47 headcollar on their horse's multiple times on a daily basis (Marlin, Williams & Pickles, In Press).
48 Almost one third of respondents had experienced a horse being injured associated with the wearing
49 of a headcollar, including 167 fatalities. In 15% of the reported headcollar incidents, a person was
50 also injured (Marlin, Williams & Pickles, In Press). Injury due to falls or being thrown from horses has
51 been the most commonly reported injury in riders whilst for riders unmounted or non-
52 riders/handlers, the most common cause of injury was reported to be kicks¹, but no reference was
53 made to headcollar related injuries to people.

54
55 The majority of headcollar-related injuries to horses in the survey by Marlin, Williams & Pickles (In
56 Press) occurred whilst they were 'tied-up' (70%). The precise circumstances of the injuries were not
57 investigated in the former study, but possible examples include a horse pulling back, the structure to
58 which the horse was secured collapsing, the horse slipping whilst tied, the headcollar getting caught
59 on a physical object or a horse getting a leg over the lead rope used to tie the horse up. Clearly, the
60 force at which a headcollar, lead rope, clip or fastener breaks or releases the horse could have a
61 significant impact on the type and severity of injury sustained in such incidents.

62
63 To date there does not appear to have been any attempt to characterise how different headcollars
64 behave when subjected to high forces. A 500kg horse pulling back at 2-3g when tied-up could result
65 in forces in excess of 10,000N. Some materials have a very high breaking point and could lead to
66 injury due to high pressures under the headcollar generated by the horse. Severe consequences of
67 headcollar-related incidents have been reported in the veterinary literature, including fracture of the
68 atlas (first cervical vertebra; the connection between the head and the rest of the skeleton)²,
69 fracture of the paracondylar process of the occiput (where the atlas connects to the skull)³ and
70 atlantoaxial subluxation (a misalignment of the 1st and 2nd cervical vertebrae)⁴. These accidents
71 often involve strangulation type events when the headcollar becomes caught on an external fixture
72 such as stable fixtures and fittings³. However, the description of the headcollars involved and the
73 nature of the injuries are generally vague or unrecorded

74
75 A number of patents exist for safety headcollars or halters. For example, a 1984 US patent
76 (US4502265A) for a "Breakaway safety halter" refers to a design "...which can release or separate
77 from each other in response to excessive longitudinal forces, such as forces in the neighbourhood of

78 30 pounds or so" (133N). No justification for this value was presented in the patent. By contrast a
79 more recent US patent (US20060185331A1) for a "Continuous duty equine halter" specifies an
80 opening force of "...in the range of 150 to 250 pounds of force", equivalent to 667-1108N, although
81 again without clear justification for the setting of the opening force.

82

83 A variety of different types of headcollar materials are commonly used in horses including leather
84 and synthetic materials such as nylon webbing, nylon rope and plastics. Headcollars are also
85 available in a standard design, which are not intended to open under force, and 'safety' headcollars
86 which are designed to open under force, although the opening force is rarely, if ever, stated. Marlin,
87 Williams and Pickles (In Press) reported that in 67% (webbing headcollar related) to 80% (lead rope
88 related) of headcollar incidents, the headcollar/lead-rope was reported to have behaved as
89 expected, i.e. if it was a safety device it is presumed to have opened and a non-safety headcollar
90 would have remained attached and intact. This calls into question whether current headcollar
91 specifications are appropriate. In addition to standard and safety headcollars, there are a variety of
92 safety devices commercially available which are designed to be attached between the headcollar
93 and lead rope, or between the lead rope and the point of fixation.

94

95 The aim of the present study was to test the force required to break, or release in the case of a
96 safety headcollar or device, a range of commercially available standard and safety headcollars, and
97 safety devices, including baler twine. In addition, the breaking force of three different strengths of
98 baler twine (synthetic twine designed for binding bales of hay, straw, or similar material) was also
99 investigated as, anecdotally, this is commonly believed to reduce the risk of injury and was reported
100 to be used by 40% of equestrians (Marlin, Williams & Pickles, In Press).

101

102 **MATERIALS & METHODS**

103 Commercially available products or materials for testing were purchased either online or direct from
104 manufacturers without specifying that these were for a research project. Products and materials to
105 be tested were chosen to represent the types of headcollars and safety devices commonly being
106 used by horse owners. These are specified in Table 1.

107

108

109 **Table 1. Products or materials tested.**

110

111

Model	Manufacturer	Size	Type	Material
Baler Twine (Fine)	Agritel Ltd	NA	Safety Device	Nylon
Baler Twine (Medium)	Agritel Ltd	NA	Safety Device	Nylon
Baler Twine (Heavy Duty)	Agritel Ltd	NA	Safety Device	Nylon
Bungee Breakaway Trailer Tie	Shires Equestrian Products	NA	Safety Device	Webbing/Elastic [#]
Cottage Craft 83	Harry Hall International Ltd	Full	Standard HC	Webbing/Fleece
Equi-Ping	Safety Release Ltd	NA	Safety Device	Plastic
FieldSafe	Horseware Products Ltd	Cob	Safety HC	Webbing
Hy Fieldsafe	Hy Equestrian	Cob	Safety HC	Webbing
Hy Soft Webbing	Hy Equestrian	Cob	Standard HC	Webbing
HyClass Leather	Hy Equestrian	Cob	Standard HC	Leather
KM Elite Webbing	KM Elite Products	Cob M	Standard HC	Webbing
Leather Foal Slip	Shires Equestrian Products	Foal	Standard HC	Leather
Libbys Field Safe	Libbys International	Full	Safety HC	Webbing
Protechmasta IR Ergonomic	Harry Hall	Cob	Safety HC	Webbing
Ready To Ride	John Whitaker International Ltd	Cob	Standard HC	Leather
Stellar (Position A)*	Equilibrium Products Ltd	Cob	Safety HC	PVC
Stellar (Position B)*	Equilibrium Products Ltd	Cob	Safety HC	PVC
Topaz	Shires Equestrian Products	Cob	Standard HC	Webbing
Vogue	Le Mieux, Horse Health Wessex Ltd	Cob	Standard HC	Webbing
Wonder Wish Adjustable Rope Halter	Wonder Wish Pet	One size	Standard HC	Nylon

112

113 HC = headcollar

114 *These positions and their effect are explained in detail on the manufacturer's website. In position A
115 the headcollar opens at 50-60kg. In position B it opens at 80-90kg.


116 # A combination of webbing and elasticated materials.

117 Manufacturer's addresses: Agritel Packaging Supplies, Agritel Ltd, Gledrid Industrial Park, Wrexham,
118 LL14 5DG, UK; Shires Equestrian Products, Leominster, Herefordshire, HR6 0QF, UK; Harry Hall
119 International Ltd, Park View Mills, Bradford, BD6 3QA, UK; Safety Release Ltd, Brickfields Stud,
120 Newmarket, Suffolk, CB8 7JH, UK; Horseware Products Ltd, Finnabair Business Park, Dundalk, Co
121 Louth, Ireland; Hy Equestrian, Battle, Hayward & Bower Ltd, Allenby Road Industrial Estate, Lincoln,
122 LN3 4NP, UK; KM Elite Products, Crawfold Business Park, Petworth, West Sussex, GU28 9JT, UK;
123 Libbys International, Alderholt, Fordingbridge, Hampshire, SP6 3AX, UK; John Whitaker International
124 Ltd, Smallbridge Business Park, Rochdale, Lancs, OL16 2SH, UK; Equilibrium Products Ltd, Unit 2,
125 Acorn Farm Business Centre, Leighton Buzzard, Beds, LU7 0LB, UK; Le Mieux, Horse Health Wessex
126 Ltd, Greenwood, Woodington Rd, Romsey, Hants, SO51 6DQ, UK; Wonder Wish Pet.
127
128

DRAFT

129 TESTING RIG

130 A frame was constructed of welded box steel sections (Figure 1). The overall dimensions of the
131 frame were 60cm x 60cm x 210cm (width x depth x height). The upright and base sections were



132

133 **Figure 1. Testing setup. A = winch; B = pulley; C = carabiner; D = crane scale; E =**
134 **headcollar/product under test; F = 15cm x 3mm steel tube.**

135

136 constructed from 50mm x 50mm x 3mm steel box lengths. The top section was constructed from
137 90mm x 50mm x 3mm sections. A section of 50mm x 50mm x 3mm steel was fixed across the base
138 and a 150mm diameter round steel tube (3mm thick), to approximate the width of a horse's poll,
139 was fixed parallel to this across the top. This allowed medium sized headcollars to hang 'naturally'
140 such that the poll ends were in line with the cheek pieces. Two sides of the frame had 3mm
141 polycarbonate sheets attached with bolts to the frame to protect the operator from projectiles due
142 to headcollar failure under load. An electric hoist with a maximum rating of 1000kg when used in
143 double cable mode and a nominal output of 1600W was attached to the bottom box section
144 (240VEHA1000, Warrior Winches, Wigan, WN6 0XQ, UK). The winch hook was attached to the
145 bottom of a battery-operated crane scale with a maximum rating of 1000kg (Model OCS-S1, Huanyu
146 Group Zhejiang High Tech Co. Ltd, Wenzhou Bridge Industrial Zone, Zhejiang, China) by a 14cm x
147 1.2cm diameter galvanised steel carabiner hook rated at 510kg (WK WLL DIN 5299 510kg J28,
148 Kleinsorge, 57439 Attendorn, Germany). The headpiece of the headcollar to be tested was passed
149 over the top of the 15cm steel tube. The top of the crane scale was connected to the ring of the
150 headcollar (where a lead rope would normally be attached) by a second steel carabiner clip. Elastic
151 bungee ropes with a rating of 40kg (Master Lock Bungi Cords, Master Lock Europe SAS, A92 400
152 Courbevoie, France) were used to stabilise the crane scale so that on failure of a headcollar the
153 crane scale would not be damaged. For testing the safety devices or baler twine that would not fit
154 over the steel tube, identical carabiner hooks were used to connect both the crane scale and
155 overhead steel tube.

156

157 TESTING PROTOCOL

158 The test articles were attached to the top round steel tube and the top of the crane scale using a
159 steel carabiner hook. The scale was then zeroed. For headcollars with size adjustment, these were
160 set to the mid-range of adjustment or the smaller size in the case of an even number of holes (e.g. if
161 there were 4 holes, then the 2nd from the top was used). If keepers were present (usually a rubber or
162 leather loop to hold excess ends of headpieces in place where the headcollar is adjustable) these
163 were always used. Force was applied in pulses by briefly activating the winch using the remote-
164 control unit. After each application of force, the scale was allowed to stabilise (1-2s) and the reading
165 in kg noted. The process was repeated until the product being tested either failed or opened in the
166 case of safety products. The process was repeated 6 times for each product. For non-safety
167 headcollars a new product was used each time. The safety devices, all of which were designed to be
168 used repeatedly, were examined visually by eye and under a magnifier and if undamaged, testing
169 was repeated on the same unit.

170


171 STATISTICS

172 Crane scale readings in kg were converted to Newtons by multiplying by the force of gravity i.e.
 173 9.807 m.s^{-2} . The existence of overall differences in opening or failure point (force) between products
 174 was evaluated with a one-way ANOVA followed by Tukeys HSD test to determine which means were
 175 significantly different (Real Statistics Release 7.5.2 with Microsoft Excel 2019 MSO 64-Bit). Separate
 176 tests were run for the headcollars and the safety products/devices. Coefficient of variation (%CV)
 177 was calculated as $\text{SD}/\text{mean} \times 100$. Data are presented as $\text{mean} \pm \text{SD}$ and significance was set at
 178 $P < 0.05$.

179


180 **RESULTS**

181
 182 An example of the 1st and 6th forcepulse curves obtained for one of the safety headcollars tested is
 183 shown in Figure 2. The mean opening force for the standard and safety headcollars are shown in
 184 Figure 3. The mean opening force ranged from 357N for the Hy Fieldsafe headcollar to 5798N for the
 185 Hy Soft Webbing Headcollar. Safety headcollars opened at the lower end of the force range whilst
 186 the standard headcollars were at the higher breaking range. The mean opening force for the two
 187 commercial non-headcollar safety devices and the three strengths of baler twine are shown in Figure
 188 4. The mean opening force ranged from 354N for fine baler twine to 1348N for heavy duty baler
 189 twine. The consistency of the different headcollars and safety devices is indicated by the coefficient
 190 of variation for the 6 tests, which are shown in Table 2. Two of the webbing headcollars, which had a
 191 coefficient of variation equal to or less than 5%, also had the 1st and 4th highest for mean opening
 192 force. The most variable items tested were fine baler twine (CV 34%) and the Bungee Breakaway
 193 Trailer Tie (CV 38%), both of which would be perceived as safety devices.




194
 195

196 Figure 2. First and sixth tests on an Equilibrium Stellar Headcollar with the popper in position A
 197 (top position and keeper in place). The solid line and dotted lines represent 2° polynomial fits
 198 thorough all points for Test 1 ($y = 9.71x^2 - 21.90x + 18.11$; $R^2 = 0.997$) and Test 6 ($y = 8.95x^2 - 17.53x$
 199 $+ 16.54$; $R^2 = 0.998$), respectively
 200



201
 202
 203 Figure 3. Opening or breaking force (N) for standard headcollars (black bars) and headcollars
 204 marketed as 'safety' headcollars (grey bars). Data are presented as mean±SD (n=6). ANOVA
 205 $P < 0.0001$. Columns with different letters differ by at least $P < 0.05$ (Tukeys HSD).
 206
 207



208
 209
 210

211 **Figure 4. Opening or breaking force (N) for fine, medium and heavy grade baler twine and two**
212 **commercially available safety devices. Data are presented as mean \pm SD (n=6). ANOVA = P<0.0001.**
213 **Columns with different letters differ by at least P<0.05 (Tukeys HSD).**
214

DRAFT

215 **Table 2. Percentage coefficient of variation, minimum and maximum opening force and range in**
 216 **force (max – min) from series of 6 tests for each product.**
 217

Product	%CV	Minimum Opening Force (N)	Maximum Opening Force (N)	Range (N)
Cottage Craft 83	4	3481	3736	255
Hy Soft Webbing	5	5296	6031	736
Stellar (Position A)	8	510	608	98
Baler Twin (Medium)	9	667	863	196
Stellar (Position B)	9	736	937	201
Libbys Field Safe	10	657	848	191
Wonder Wish Adjustable Rope	11	3334	4413	1079
KM Elite	12	3825	5100	1275
FieldSafe	12	1373	2010	637
Leather Foal Slip	13	961	1383	422
Hy Fieldsafe	14	304	441	137
Ready To Ride	16	1667	2285	618
Vogue	16	2795	4021	1226
Topaz	16	2462	3678	1216
Protechmasta IR Ergonomic	16	525	834	309
HyClass Leather	19	1863	2452	588
Baler Twine (Heavy duty)	23	1059	1912	853
Equi-Ping	24	574	1108	534
Baler Twine (Fine)	34	181	500	319
Bungee Breakaway Trailer Tie	38	432	1295	863

218
219

220 All of the commercial safety devices tested were designed to be reset after opening and used again.
221 This included FieldSafe, Hy Fieldsafe, Libbys Field Safe, Protechmasta Infrared Ergonomic, Stellar
222 (Position A), Stellar (Position B), Equi-Ping and Bungee Breakaway Trailer Tie. There was no
223 significant difference in mean opening force across all devices between the 1st (854±530N), 2nd
224 (854±425N), 3rd (775±319N), 4th (778±463N), 5th (805±439N) and 6th tests (873±430N)(ANOVA F
225 =0.075; P=1.0).

226

227 **DISCUSSION**

228

229 Limitations of the present study: the headcollars and safety devices were only tested by pulling in
230 one plane, equivalent to a pull at 180° to the horse's poll. However, when horses are tied-up and
231 pull backwards this would most likely represent the direction of force application. The safety
232 headcollars tested were also all designed to open when force was applied in this direction. However,
233 baler twine loops, the Equi-Ping and Bungee Breakaway Trailer Tie would all be able to release in
234 response to loading at different angles to the attachment between the device and headcollar. The
235 method of testing applied small pulsatile loads to the headcollars and devices tested. The opening or
236 breaking force may be different for continuous incremental application of force or rapid application
237 of force, as in a drop test, compared with the pulsed application used. Finally, some devices tested
238 produced high coefficients of variation. As other devices produced low coefficients of variation and
239 as all devices were tested in the same way, it would be reasonable to conclude that the variability
240 was in the device/equipment tested as opposed to the test procedure.

241

242 One of the remarkable features of these results is the range of breaking/opening forces of the
243 devices and headcollars tested from as low as ~350 up to close to 6000N. A force of 6000N equates
244 to a load of 611kg. Thus, a 500kg horse could potentially be suspended by a headcollar of this
245 strength, provided the lead rope was of a similar strength. Using the same testing setup as reported
246 here, we have measured lead rope failure in five different commercial products of between 1470
247 and 4700N. Similarly, there is likely to be an increased risk of injury to the handler if they become
248 entwined in a headcollar/lead rope, when a horse pulls back and exerts a high force if the breaking
249 force is high. Experimental fracture loads in the human forearm are reported to be between 707 –
250 5821 N, averaging 3180 N⁵⁶ suggesting the breaking forces reported here could be extremely
251 dangerous and contribute to significant damage to human soft tissue and bone as a result of the
252 headcollar and/or safety device not breaking. Therefore, it could be recommended that headcollars
253 with high opening/breaking forces are not left on unsupervised horses e.g. at pasture, when
254 travelling, or when tied-up. Such headcollars may also present a risk of injury to handlers. In
255 addition, it could also be recommended that such headcollars, if used to restrain horses, are not

256 used without a secondary safety device of some kind. There may however be circumstances in which
257 a headcollar with a very high breaking force would be preferable, for example if leading horses in
258 potentially dangerous environments, such as along roads or when loading/unloading at ports and
259 airports.

260

261 Anecdotally, there is a widespread perception that leather headcollars are 'safer' than synthetic,
262 nylon or webbing headcollars as they would break at a lower force. For the two models of standard
263 (non-safety) leather headcollars tested, these indeed both broke at lower forces than the majority of
264 webbing headcollars tested. This observation is also consistent with the fact that leather headcollars
265 were reported to have a lower injury rate compared with synthetic or webbing headcollars (Marlin,
266 Williams & Pickles, In Press).

267

268 Headcollar-related injuries could be expected to fall into several categories, including pressure-
269 induced lesions of superficial anatomical structures, traumatic injuries to deeper structures, injuries
270 to the neck distal to the attachment of the headcollar and other injuries potentially as a result of
271 horses falling. The true incidence of such injuries is unknown as they are rarely reported and are
272 often suspected rather than observed. Force-related tissue damage can occur over prominent bony
273 areas with little overlying tissue; as such the head is vulnerable. If normal capillary pressure is
274 exceeded, surrounding and underlying tissues become anoxic. If this pressure is sustained for a
275 critical duration, cell death occurs resulting in tissue necrosis. The most common cause of pressure-
276 related headcollar injury is probably paresis of the buccal branch of the facial nerve which can occur
277 under general anaesthesia if the headcollar cheek piece of the dependent side is not sufficiently
278 padded. The facial nerve is particularly at-risk during surgeries involving the head or eye, when
279 surgical manipulations may subject the head to extra weight or pressure ⁷. Facial nerve paralysis in a
280 horse has also been reported following 'rope recovery' from general anaesthesia which suggests the
281 rope recovery system (i.e. headcollar with attached rope) may have resulted in an increased
282 pressure on the head ⁸.

283

284

285 When force is focussed on a known area we discuss the implications for tissue damage in terms of
286 pressure per unit area i.e. Pressure (Pa) = Force (N) / Area (m²). Tissue damage as a result of
287 pressure is due to a combination of the absolute pressure and the duration of application of the
288 pressure. In people, pressure ulcers (sores) are typically the result of damage caused to the skin and
289 underlying tissue by long-term contact due to pressure, shear, friction and moisture. Depending on
290 the orientation of the patient, mean surface pressure on different parts of the body in human
291 subjects ranged from 0 to 24kPa ⁹. Using canine models, the threshold for pressures leading to

292 pressure ulcers has been proposed to be only 4.3kPa^{10 11}. However more recent studies have
293 suggested thresholds of around 9kPa¹² or even 32kPa^{13 14}. But these are forces which lead to ulcers
294 over prolonged periods of time and it is unlikely that a horse would have high pressure applied by
295 the headpiece of a headcollar for more than a matter of minutes. In horses, Nykios et al.¹⁵ proposed
296 pressure thresholds of 11kPa for mean pressure and 31kPa for peak pressure for pain or tissue
297 damage on the horses back under the saddle area. In a preliminary study of the pressure on the poll
298 under a synthetic headcollar headpiece in a horse being led at walk and trot, peak pressures of
299 50kPa at walk and 60kPa at trot were recorded (Godoy & Marlin, unpublished observations). For a
300 headpiece of 3cm width and assuming half of the circumference was in contact with the 15cm
301 diameter steel tube ($2 \times \pi \times r / 2 = 23.6\text{cm}$), the area of contact would be $23.6\text{cm} \times 3\text{cm} = 70.8\text{cm}^2$.
302 At a force of 2000N (the lowest breaking force of a conventional headcollar, this would represent an
303 average pressure of $28.2 \text{ N/cm}^2 \times 10 = 282\text{kPa}$. For the highest breaking force this would represent
304 an average pressure of 818 kPa.

305

306 Conclusion

307 The force at which safety headcollars and safety devices opened and conventional headcollars failed
308 showed a considerable range and some products or devices showed a high variation in test to test.
309 However, all safety devices and 'baler twines' opened at a lower mean forces than all headcollars
310 failed, with the exception of the foal slip tested. . These findings are generally consistent with a
311 recent survey of horse owners (Marlin, Williams & Pickles, In Press) concerning headcollar use and
312 headcollar related incidents and injuries. At present there do not appear to be any industry
313 standards for headcollar or headcollar safety device standards and it is proposed that
314 manufacturers, welfare bodies and equestrian stakeholders give this issue serious consideration as a
315 priority..

316

317 **Conflict of Interest Statement**

318 This study was commissioned and funded by Equilibrium Products Ltd. Equilibrium Products Ltd
319 specified, purchased and supplied the products/materials to be tested with the exception of the
320 baler twine (Agritel Packaging Supplies Ltd). The testing rig and testing protocol was built and
321 designed by one of the authors (DM). Equilibrium Products Ltd were shown a final copy of the
322 manuscript but had no involvement in the analysis, writing or presentation of results or in the final
323 conclusions presented.

324

325 **Acknowledgments**

326 We would like to thank Agritel Packaging Supplies Ltd for supplying the samples of baler twine.

327

DRAFT

REFERENCES

- 329
330
331 1 Hawson, L.A., McLean, A.N. and McGreevy, P. D. The roles of equine ethology and
332 applied
333 learning theory in horse- related human injuries. *Journal of Veterinary Behavior: Clinical*
334 *Application and Research*. 2010; 5:324-338.
335
336
337 2 Volcholrt, W. [Atlas fracture in a foal following wrong accustoming to halter]. *Dtsch*
338 *Tierarztl Wochenschr*; 1972; Jul 1;79(13):323.
339
340 3 Lischer, C.J., Walliser, U., Witzmann, P., Wehrli Eser, M., Ohlerth, S. Fracture of the
341 paracondylar process in four horses: advantages of CT imaging. *Equine Vet J*. 2005
342 Sep;37(5):483-7.
343
344 4 Nixon, A.J. and Stashak, T.S. (1988) Laminectomy for relief of atlantoaxial subluxation
345 in four horses. *J Am Vet Med Assoc*. Sep 15;193(6):677-82.
346
347 5 Ashe, M.C., Khan, K.M., Kontulainen, S.A., Guy, P., Liu, D., Beck, T.J. and McKay, H.A.
348 Accuracy of pQCT for evaluating the aged human radius: an ashing, histomorphometry
349 and failure load investigation. *Osteoporosis International*, 2006; 17, 1241-1251
350
351 6 Ural, A., Prediction of Colles' fracture load in human radius using cohesive finite
352 element modeling. *Journal of biomechanics*; 2009; 42(1), pp.22-28.
353
354 7 Wagner, A.E. Complications in equine anaesthesia. *Vet Clin North Am Equine Pract*.
355 2008; Dec;24(3):735-52.
356
357 8 Niimura del Barrio, M.C., David, F., Hughes, J.M.L. *et al*. A retrospective report (2003–
358 2013) of the complications associated with the use of a one-man (head and tail) rope
359 recovery system in horses following general anaesthesia. *Ir Vet J*; 2018; **71**, 6.
360

- 361 9 Mimura, M., Ohura, T., Takahashi, M., Kajiwara, R., & Ohura Jr., N. Mechanism
362 leading to the development of pressure ulcers based on shear force and pressures
363 during a bed operation: Influence of body types, body positions, and knee positions.
364 *Wound Repair and Regeneration*; 2009; 17(6), 789–796.
365
- 366 10 Kosiak, M. Etiology of and pathology of ischemic ulcers *Arch Phys Med Rehabil* 1959;
367 40: 62–9.
368
- 369 11 Kosiak, M. Etiology of decubitus ulcers (1961). *Arch Phys Med Rehabil* 1961; 42: 19–
370 29.
371
- 372 12 Sachse RE, Fink SA, Klitzman B. Multimodality evaluation of pressure relief surfaces.
373 *Plast Reconstr Surg*; 1998; 102: 2381-2387.
374
- 375 13 Gefen. A., Gefen, N., Linder-Ganz, E., Margulies, S.S. In vivo muscle stiffening under
376 bone compression promotes deep pressure sores. *J Biomech Eng*; 2005; 127: 512–24.
377
- 378 14 Linder-Ganz E, Shabshin N, Itzchak Y, Gefen A. Assessment of mechanical conditions
379 in sub-dermal tissues during sitting: a combined experimental-MRI and finite element
380 approach. *J Biomech*; 2007; 40: 1443–54.
381
- 382 15 Nyikos, S., Werner, D., Müller, J.A., Buess, C., Keel, R., Kalpen, A., Vontobel, H-D., von
383 Plocki, K.A., Auer, J.A. von Rechenberg, B. Elektronische Satteldruckmessungen im
384 Zusammenhang mit Rückenproblemen bei Pferden. *Pferdeheilkunde*; 2005; 21(3)
385 (Mai/Juni), 187-198.
386